

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Tire Selection & Rims GVWR-64536KG	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Windows, Roofs & Partitions Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Tire Selection & Rims GVWR > 4536kg & MC	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	138	Tire Pressure Monitory Systems	Vehicle-19	TEST
27	139	New Pneumatic tires for light vehicles	Equip.-9	TEST
28	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
29	202	Head Restraints	Vehicle-15	TEST
30	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
31	204	Steering Control Rearward Displacement	Vehicle-17	TEST
32	205	Glazing Materials (Inspection)	Equipment	Insp.-6
33	206	Door Locks & Door Retention Components	Equip.-8	TEST
34	207	Seating Systems	Vehicle-18	TEST
35	208	Occupant Crash Protection	Vehicle-20	TEST
36	209	Seat Belt Assemblies	Equip.-10	TEST

37	210	Seat Belt Assembly Anchorages	Vehicle-21	TEST
38	212	Windshield Mounting	Vehicle-22	TEST
39	213	Child Restraint Systems	Equip.-11	TEST
40	214	Side Impact Protection	Vehicle-23	TEST
41	216	Roof Crush Resistance	Vehicle-24	TEST
42	217	Bus Window Retention & Release	Vehicle-25	TEST
43	218	Motorcycle Helmets	Equip.-12	TEST
44	219	Windshield Zone Intrusion	Vehicle-26	TEST
45	220	School Bus Rollover Protection	Vehicle-27	TEST
46	221	School Bus Body Joint Strength	Vehicle-28	TEST
47	222	School Bus Passenger Seating	Vehicle-29	TEST
48	223	Rear Impact Guards	Equip.-13	TEST
49	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
50	225	Child Restraint Anchorage Systems	Vehicle-30	TEST
51	301	Fuel System Integrity	Vehicle-31	TEST
52	302	Flammability of Interior Materials	Equip.-14	TEST
53	303	Fuel System Integrity of CNG Vehicles	Vehicle-32	TEST
54	304	CNG Fuel Container Integrity	Equip.-15	TEST
55	305	Electric Vehicles	Vehicle-33	TEST
56	401	Interior truck Release	Vehicle-34	TEST
57	403	Platform Lift Systems for Motor Vehicles	Equip.-16	TEST
58	404	Platform Lift Installations In Motor Vehicles	Vehicle-35	TEST
59	500	Low Speed Vehicle Requirements	Vehicle-36	TEST
SUMMARY: 36 vehicle standards, 16 equipment standards, 7 inspection standards				

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: JULY 15, 2009

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

REPORTS ACCEPTED DURING JUNE 2009 FOR FY 2009 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
111	KAR 001	FORD	2009 FORD EDGE MPV 4-DOOR	PASS 640486
114	GTL 005	GMC	2009 CHEVROLET COBALT 4-DOOR SEDAN	PASS 640463
114	GTL 006	HONDA	2009 HONDA ACCORD 4-DOOR SEDAN	PASS 640490
114	GTL 007	GMC	2009 CADILLAC CTS 4-DOOR SEDAN	PASS 640462
118	KAR 001	FORD	2009 FORD EDGE MPV 4-DOOR	PASS 640487
135	TRC 010	TOYOTA	2009 LEXUS ES350 MPV 4-DOOR	PASS 640470
135	TRC 011	MAZDA	2009 MAZDA 3 4-DOOR SEDAN	PASS 640471
201	CAL 005	NISSAN	2009 NISSAN SENTRA 4-DOOR SEDAN	PASS 640495
201	MGA 001	GMC	2009 CHEVROLET MALIBU 4-DOOR SEDAN	PASS 640472
201	MGA 002	GMC	2009 CHEVROLET TRAILBLAZER MPV 4-DOOR	PASS 640473
201	MGA 003	FORD	2009 FORD FLEX MPV 4-DOOR	PASS 640474
206	KAR 007	TOYOTA	2009 TOYOTA YARIS DOOR LATCH/HINGE	PASS 640482
209	DTB 001	FORD	2009 FORD FLEX REAR LEFT SEAT BELT ASSY.	PASS 640483
209	UST 016	NISSAN	2009 NISSAN MURANO DRIVER SEAT BELT ASSY.	PASS 640488
209	UST 017	NISSAN	2009 NISSAN PATHFINDER DRIVER SEAT BELT ASSY.	PASS 640485
209	UST 018	NISSAN	2009 NISSAN ARMADA DRIVER SEAT BELT ASSY.	PASS 640489
213	UST 046	GRACO	2009 GRACO ASSURA INFANT CHILD RESTRAINT	PASS 640476
213	UST 047	GRACO	2009 GRACO SNUGRIDE INFANT CHILD RESTRAINT	PASS 640477
213	UST 052	GRACO	2009 GRACO COMFORT SPORT CONV. CHILD RESTRAINT	PASS 640497
213	UST 053	GRACO	2009 GRACO NAUTILUS COMB. CHILD RESTRAINT	PASS 640484
213	UST 060	RECARO	2009 RECARO SIGNO CONV. CHILD RESTRAINT	PASS 640464
213	UST 061	IMMI	2009 SAFEGUARD CHILD SEAT TODDLER CHILD RESTRAINT	PASS 640466
213	UST 49B	GRACO	2009 GRACO INFANT SAFESEAT CHILD RESTRAINT	PASS 640478

REPORTS ACCEPTED DURING JUNE 2009 FOR FY 2009 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
213	UST 050	GRACO	2009 GRACO SAFESEAT STEP 2 CHILD RESTRAINT	PASS 640480
213	UST 051	GRACO	2009 GRACO COZYCLINE TODDLER CHILD RESTRAINT	PASS 640481
213	UST 054	GRACO	2009 GRACO ULTRA CARGO COMB. CHILD RESTRAINT	PASS 640479
213	UST 61B	IMMI	2009 SAFEGUARD GO HYBRID BOOST CHILD RESTRAINT	PASS 640467
218	ACT 002	NOLAN	2008 NOLAN N103 N-COM COMP. MOTORCYCLE HELMET	PASS 640475
222	MGA	COLLINS	2008 COLLINS GRAND BANTAM SCHOOL BUS	FAIL-P ¹ 640459
403	MGA 004	BRAUN CORP.	2008 BRAUN VANGATER PRIVATE USE	FAIL-LPI ² 640469
404	MGA 001	COLLINS BUS CORP.	2008 COLLINS GRAND BANTAM SCHOOL BUS	FAIL-P ³ 640468

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L - LABELING

¹ Barrier performance failure, under review

² Platform interlock stowing, outer barrier test, impact test, over load test, labeling, platform trans., under review

³ The platform lift does not comply with the applicable requirement, under review

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JUNE 2009
(CI NUMBER SYSTEM EXAMPLE: "CI-208-071220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2008)**

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JUNE 2009
(PE NUMBER SYSTEM EXAMPLE: "PE-208-071220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2008)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-080618C	Poweramper/2008 Poweramper /Physical Inspection	MI
PE-108-080720A	Fashtek/2008 Fashtek /Physical Inspection	MI
PE-108-080820F	Xenon Eyes/2008 Xenon Eyes/Physical Inspection	MI
PE-108-080918E	Matrix Racing/2008 Matrix Racing/Physical Inspection	MI
PE-108-090129A	Hid Outlet/2009 Hid Outlet/Physical Inspection	MI
PE-108-090324A	Haining Mozo Technologies/HID Conversion	CP
PE-108-090320A	Metra Electronics/2009 Metra Electronics/HID Conversion	CP
PE-218-080925A	Queen Kuan Enterprise Co., Ltd./2008 AFX FX-28/Penetration Failures	CT
PE126-090402A	Mazda Motor Corp./2009 Mazda 3/Data Request	CT
PE-222-090504A	Blue Bird Body Co./2009 Blue Bird Microbird/Knee form requirements	CT
PE-222-090521A	Collins Bus Corp/2008Collins Grand Bantam/Barrier performance forward	CT

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-090128A	Ikon Auction/2009 Data Request	MI
PE-222-090617A	Girardin Minibus/2008 Girardin G5 Mb-iv 200c/Barrier performance forward	CT

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-218-080817A	KBC Helmet Co., Ltd./2008 KBC Magnum/Penetration Failures/Manufacturer's noncompliance report 6/10/2009
PE-222-090617A	Girardin Minibus/2008 Girardin G5 Mb-iv 200c/Barrier performance forward/ Closed by NHTSA 6/25/2009

CAUSE:

PE Petition
 CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Mfgr. Inquiry
 MD Mfgr. Defect